



FFR 199

FIGURE 5. Trench log by Converse Ward Davis Dixon (1979b) at locality 2, Figure 3, showing intersection of slide planes and fault at bottom center of trench and location of C₁₄ samples below plane at right.